

# General Guidelines for Crash Analysis in LS-DYNA®

Suri Bala  
Jim Day

© Copyright Livermore Software  
Technology Corporation



Copyright © 2003-2012 by LIVERMORE SOFTWARE TECHNOLOGY CORPORATION

Crash Guidelines p. 21.1

## Modeling Guidelines for Crash Analysis

### ■ Element Shapes

- Avoid use of triangular shells, tetrahedrons, pentahedrons whenever possible (OK in rigid bodies).
- ESORT=1 if triangular shells are present, \*CONTROL\_SHELL.
- ESORT=1 if tetrahedrons, pentahedrons are present, \*CONTROL\_SOLID.



### ■ Warping Stiffness in Shells

- Warped shells are too soft.
  - For warped B-T shells, use \*CONTROL\_SHELL to set BWC=1 and invoke the more costly full projection for warping stiffness (PROJ=1) since drill projection inhibits rigid body rotation.
  - For fully-integrated shell ELFORM=16, set hourglass formulation IHG to 8 to invoke warping stiffness.



Copyright © 2003-2012 by LIVERMORE SOFTWARE TECHNOLOGY CORPORATION

Crash Guidelines p. 21.2

## Modeling Guidelines for Crash Analysis

### ■ Shells

- Invoke invariant node numbering (INN=2 in \*CONTROL\_ACCURACY) so that results are insensitive to the order of the nodes in the element connectivity.
- Shell thickness update (ISTUPD in \*CONTROL\_SHELL) is generally not needed for crash analysis (req'd for metal forming).
  - If thinning is needed, invoke selectively (by parts) via PSSTUPD and use more stable ISTUPD=4
- Use minimum of 3 integration points through the thickness (NIP in \*SECTION\_SHELL) for shell parts undergoing plastic deformation.
- Set shear factor in \*SECTION\_SHELL to theoretical value of 5/6 or invoke Laminated Shell Theory by setting LAMSHT=3 in \*CONTROL\_SHELL.
- Turn on bulk viscosity for shells by setting TYPE = -1 \*CONTROL\_BULK\_VISCOSITY

### ■ Solids

- Use ELFORM=1 for solids and include appropriate HG control



## Modeling Guidelines for Crash Analysis

### ■ Hourglass Control

- If using \*CONTROL\_HOURLASS, define part-specific \*HOURLASS cards to overwrite the global hourglass definitions where appropriate.
  - Be careful when importing validated barrier/head models
- Recommend stiffness hourglass control, IHQ=4, with hourglass coefficient QM = 0.03 for metal and plastic parts.
- Recommend HG type 6 with HG coefficient between 0.5 and 1.0 for foams and rubbers
  - In soft materials, stiffness-based hourglass control (types 4 and 5) likely causes overly stiff response even with a reduced hourglass coefficient.



## Modeling Guidelines for Crash Analysis

- Materials
  - When including strain rate effects in plasticity models, set  $VP=1$ .
    - Uses plastic strain rate rather than total strain rate.
    - Results in smoother response
  - Stress-strain curves should be smooth, especially for foams.
  - Mass of null shells and null beams is included in total mass.
    - Unless additional mass is intentional, set density of null shells and beams to a small value.
  - Curves defining constitutive data should have abscissa values in the anticipated working range. Curves will be extrapolated by LS-DYNA® if necessary.



## Modeling Guidelines for Crash Analysis

- Connections
  - Nodal rigid bodies
    - Avoid 1-noded RB's and nodal rigid bodies with numerically insignificant inertia as these rigid bodies are deleted and a warning is issued to the *d3hsp* file.
  - Joints
    - Joint node pairs should be a reasonable distance apart.
    - When increasing joint penalty factor to take out 'slop' in penalty-based joint, the time step scale factor may need to be reduced to avoid instability.



## Modeling Guidelines for Crash Analysis

- Connections
  - Discrete springs
    - Spring nodes cannot be massless.
    - If `_NONLINEAR` spring material is used, define stiffness in compression and tension.
    - Use only N1 to N2 orientation.
  - Deformable spotwelds
    - Avoid "free/suspended" spotwelds.
    - Look out for spotweld nodes that are not tied (see warnings in d3hsp).
    - Exclude spotwelds from contact (automatic if `*MAT_SPOTWELD` is used)
    - Invoke stiffness damping in shells if using `*CONTACT_SPOTWELD_TORSION`
    - Solid spotwelds show promise.
      - Less sensitive to spotweld placement
      - Beam spot welds can be converted to solid spot welds automatically using `*CONTROL_SPOTWELD_BEAM`



## Modeling Guidelines for Crash Analysis

- Rigid Bodies
  - Refined mesh of rigid bodies encouraged.
    - Added expense is minimal.
    - More realistic mass properties and distribution of contact forces.
  - Specify reasonable elastic constants for `*MAT_RIGID`, e.g., those of steel.
    - Affects contact stiffness unless `SOFT=2`.
  - Do not impose constraints on nodes of rigid bodies. Impose constraints on card 2 of `*MAT_RIGID` or using the `_SPC` option for the `*CONSTRAINED_NODAL_RIGID_BODY` command.



## Modeling Guidelines for Crash Analysis

### ■ Initial Velocity

- Be careful with rigid body initial velocities.
  - There is a hierarchy to the commands that specify initial velocity for rigid bodies: \*INITIAL\_VELOCITY\_RIGID\_BODY, \*INITIAL\_VELOCITY with IRIGID flag on, \*PART\_INERTIA, \*INITIAL\_VELOCITY\_GENERATION
  - If initial velocity of rigid bodies is inexplicably off, use double precision or use \*INITIAL\_VELOCITY\_RIGID\_BODY command.
- Make final check of initial velocity with a plot of velocity vectors at time = 0.

### ■ Parallel Processing

- For SMP, turn on consistency flag with `ncpu=-|#procs|` on execution line.



## Modeling Guidelines for Crash Analysis

### ■ Contact

- Take care to account for shell thickness when generating the mesh.
- Avoid redundant contact definitions.
- Use only AUTOMATIC contacts.
- Increase contact thickness for very thin shells to prevent release of contact.
- Use of IGNORE=2 or SOFT=2 is encouraged for contact in cases where small initial penetrations are reported.
- Use of SOFT=1 is preferred over SOFT=0, especially in treating contact between dissimilar materials.
- Use SOFT=2 for contact surfaces with sharp corners.
- Use AUTOMATIC\_GENERAL for beam-to-beam contact.



## Modeling Guidelines for Crash Analysis

- Postprocessing
  - Animate results to check for nonphysical behavior, for example, parts noticeably penetrating other parts.
  - Check energies in *gstat* and *matsum*
    - Use \*CONTROL\_ENERGY to turn on computation of relevant energy values.
    - Energy ratio should remain close to 1.0.
    - Hourglass energy < 10% of peak internal energy.
    - If no contact friction, contact energy in *gstat* should be elastic and thus near zero when parts are no longer in contact.
    - If contact friction is nonzero, contact energy should be positive and not necessarily small.
  - When using mass scaling, check added mass in *gstat*. Added mass sensitivity study is suggested to justify use of added mass.

