Introduction to LS-PrePost (workshops)

Quanqing Yan, Philip Ho, LSTC

2018



Table of Contents

SECTION	WORKSHOPS
Overview	-
General Operations	Workshop 1
Mesh Generation	Workshop 2
Pre-Processing	Workshop 3-4-5
Post-Processing	Workshop 6

Overview

About LS-PrePost

- LS-PrePost is an advanced pre and post-processor designed specifically for LS-DYNA
- LS-PrePost is developed for Windows and Linux
- LS-PrePost is Free
- Core Functionality
 - Full support of LS-DYNA keyword files
 - Full support of LS-DYNA results files
 - Robust handling of geometry data (including CAD engine)
 - Pre-processing (meshing, model clean-up, entity creation)
 - Post-processing (animation, fringe plotting, curve plotting)

Online Resources

- Official Website
 - http://www.lstc.com/lspp
- User Group
 - http://groups.google.com/group/ls-prepost
- Latest Release Version:
 - http://ftp.lstc.com/anonymous/outgoing/lsprepost/4.5/
 - ftp://ftp.lstc.com/outgoing/lsprepost/4.5/
- Beta Version:
 - http://ftp.lstc.com/anonymous/outgoing/lsprepost/dev
- Training notes:
 - ftp://ftp.lstc.com/outgoing/qyan/Class


Workshop 1 General Operations


- Parts on/off
- Render buttons (bottom toolbar)
- Group, appearance and view
- Identify and find
- Element blank(mask)
- Part color

Workshop 1

Load and view an LS-DYNA Keyword file...


- Launch a new session of LS-PrePost
- File > Open > LS-DYNA Keyword File (select /workshop1/belted.k)
- Use Shift + Left Click to rotate the model
- Click render buttons (1) ---- (9)






Use the part on/off interface...


- Go to Model → SelPart ("Assembly and Select Part") and select individual parts from the list
- Use Ctrl + Left Click to select multiple parts
- Click All to display all parts
- Toggle Beam / Shell / Solid / Disc / Sbelt
- Click SortBy button and turn on/off some check boxes in the setting columns in the Part Sort dialog
- Click the MatTypeName header to see the sorting effect
- Click **Done** in sort part






Create a part group...


- Go to Model → Groups
- Click Create (all visible parts will be saved to "Group_43")
- Select "SetP94" from the list
- Click Select
- Select "Group_43" from the list
- Click Select






Modify part appearance...


- Go to Model → Appearance
- Select any one of the drawing modes Hide / Edge / View/ Wire in the Appearance interface
- Pick some parts in the model
- Toggle Thick in the Appearance interface and pick the roof parts
- Click the **Zoom In** render button (or hit Ctrl+Z) and zoom in on a shell part to verify that thickness is displayed





Create a view...

- Go to Model → Views
- Click Create (the current view will be saved as "View_01")
- Rotate the model and click Create again (saved as "View_02")
- Select "View_01" from the list
- Click Select
- Select "View_02" from the list
- Click Select





Identify nodes and elements...

Turn on the mesh (using the Mesh render button)




- Go to Element Tools → Identify
- Select **Node** in the Identify interface and pick some nodes in the model to display their IDs
- Select Element in the Identify interface and pick some elements
- Toggle Elem Dir to display the N1 to N2 direction
- Click the Clear All button to clear all highlighted entities






Find a node and element...


- Go to Element Tools → Find and select Show Only
- Enter 1439 in the text field and click Find
- Click Neighbors several times
- Click UnblankAll button
- Select **Node** in the Find interface
- Enter 5340 in the text field and click Find
- Click Neighbors several times




Blank some elements...

- Go to Element Tools → Blank
- Select Area in the General Selection interface and draw a box to blank some elements
- Click Reverse in the Blank interface
- Click Unblank All in the Blank interface
- Click the Assembly and Part (SelPart) render button
- Select "88 PSHELL" from the list, click the Auto Center (AutCen) render button, and click Done in the Assembly and Part interface
- Toggle Prop (propagate) in the General Selection interface, select
 Ang: 15, and pick an element on the front of the torso







Modify part color...


Click the Activate All render button




- Go to Model → PtColor
- Select Color
- Adjust color using the RGB sliders
- Select **Set** and pick some parts
- Select any color from color map

Click **Backg** (only works when View > Background >


Plain is selected)






Modify part transparency...

- Select Transparency
- Pick the roof of the structure and adjust the slider
- Select Pick Through and pick through the roof to make some additional components transparent
- Click Active and drag the slider to the far left
- Click Rstp button (reset all parts to opaque)
- Click Amap button (reset parts color by color map)





Workshop 2Mesh Generation

- Shape mesh
- ❖ N-line mesh
- Auto mesh
- Solid mesh


Workshop 2

Create a solid cylinder...

- Launch a new session of LS-PrePost
- Go to Mesh → Shape Mesher
- Select Entity: Cylinder_Solid
- Enter Radius: 5, Length: 10,

Num Ele (Circumferential): 32, Num (Length): 20

- Enter XYZ: 0,0,1 for position
- Click dirz (set direction to 0,0,1)
- Click Create and Accept



Create a shell cylinder...

Select Entity: Cylinder_Shell

Enter Num Ele: 30 (leave other parameters unchanged)

Enter XYZ: 15,0,1 for position


Activate Top And Bottom (meshes ends of cylinder)


Click Create and Accept

Turn on the mesh (using the Mesh render button)

 Rotate the model such that you can see the crosssection of both cylinders (note the different cross-sectional mesh of the two


parts)






Create a mesh from 4 lines...


- Launch a new session of LS-PrePost
- File > Open > IGES File (select /workshop2/test_4lmesh_curves.igs)
- Click Open in the IGES Read Options popup
- Go to Mesh → N-Line Mesher
- Select Type: 4 Line Shell
- Pick the longest curve
- Pick the remaining curves in clockwise order
- Enter N1: 24 and hit Enter
- Enter N2: 12 and hit Enter
- Enter N3: 20 and hit Enter
- Enter N4: 10 and hit Enter
- Click Mesh It and Accept






Sweep one line along another...


- Launch a new session of LS-PrePost
- File > Open > IGES File (select /workshop2/sweep_lines.igs)
- Click Open in the IGES Read Options popup
- Go to Curve → Circle
- Select Method: Parameters
- Click the "." button next to Origin Point X
- Select **Geometry** in the Create Position interface
- Pick the endpoint of the remaining curve
- Click **Done** in the Create Position interface
- Enter Direction X Y Z: 1 0 0
- Enter Radius: 50 and click Apply




Sweep one line along another...

- Go to Mesh → N-Line Mesher
- Select Type: Line sweep
- Select Mesh By: Number of elements
- Pick the circle as L1
- Pick the red line as L2
- Click the up arrow near L1 several times to increase N1 to 15
- Click the up arrow near L2 several times to increase N2 to 20
- Enter Part ID: 2
- Click Mesh It and Accept










Auto mesh an STEP file using Auto mesh...

- Launch a new session of LS-PrePost
- File > Open > STEP File (select /workshop2/bottle.stp)
- Click Open in the Open File Options popup
- Click the **IsoMetric** render button
- Go to Surf → MidSurf
- Select Method By Solid
- Pick Solid 1
- Activate Stitch Mid-Surfs
- Click Apply
- Click Close









Auto mesh an STEP file using Auto mesh...

Inactivate Soild 1 in feature tree






Purpose: Auto mesh an STEP file using Auto mesh...

- Go to Mesh → AutoM
- Select mesh mode by Size
- Enter Elem Size : 1.0
- Click Active on Sel. geom interface
- Click Mesh
- Click Accept
- Click Done
- Click EdgGeo render buttons turn geometry off





Workshop 3 Model Editing


- Model free edge
- Duplicate nodes merge
- Node and element Editing
- Fill holes
- Element normal align
- Save a keyword file

Workshop 3

Merge duplicate nodes...


- Launch a new session of LS-PrePost
- File > Open > LS-DYNA Keyword File (select /workshop3/badmesh.k)
- Go to Element Tools → Duplicate Nodes and turn on the mesh (using the Mesh render button)
- Activate Show Free Edges
- Enter Tolerance: 1.0
- Click Show Dup Nodes (see figure)
- Click Merge Dup Nodes
- Click Accept
- Click Done






Replace nodes...


- Go to Element Tool → Node Editing
- Select Replace
- Select Area and MidPoint
- Zoom in the internal free edges area, select two nodes at a time for merging (by drawing a window)
- Click Accept
- Repeat 4 and 5 until all internal free edges have been eliminated






Create a tria element...

- Go to Element Tool → Element Editing
- Select Create
- Select Elem Type: Shell
- Activate PID and pick the part
- Activate Tria Only
- Pick the 3 nodes to fill the final gap in the part
- Click Accept





Align nodes along a line...

- Go to Element Tool → Node Editing
- Select Align
- Click the Right render button
- Click the **Zoom In** render button and zoom in as shown
- Pick 2 nodes to form a line
- The yellow dots shows the nodes will be align
- Click Align

Click Accept


2

3459

3

3

3



Split elements...

Go to Element Tool → Element Editing

ByNode

ByGPart

BySegn ByCurve)

BySurf

Adiacent

Attach

Clear

Load Deselect


Whole


Add 🌘

- Select **Split/Merge**
- Activate Constrain Adaptive
- Pick the elements around the hole as shown (use **ByPath** filter in the General Selection interface)
- Click Apply

Click Accept

Sel. Shells(0)







Label selection 3DSurf


Fill a hole...

- Go to Mesh → Element Generation
- Select Shell
- Select Shell By: Fill_Holes
- Type 1 in Part ID
- Pick any one node on the perimeter of the hole
- Click Create
- Click Accept






Align shell normals...



Save the modified input file...

- File > Save As > Save Keyword As...
- Click Browse
- Enter a file name (save as /workshop3/goodmesh.k)
- Click Save




Workshop 4Build a fan model

- Create a surface
- Surface mesh
- 2Line mesh
- Part trim
- Model transform (rotate)
- Save a keyword file

Workshop 4


Create a surface...


- Launch a new session of LS-PrePost
- File > Open > IGES File (select /workshop4/hub.igs)
- Rotate model as shown in figure
- Go to Surf \rightarrow N-Side
- Pick edge **8,5,6,7** then click **Apply**



Surface mesh...

- Go to Mesh → AutoM
- Select mesh mode by Size
- Fnter Flem Size: 3.0
- Pick Face 1 then click Mesh
- Click Accept
- Click Done





Search


Undo


Close

Hub mesh(sweep)... X N-Line Mesher Go to Mesh → NlineM Type Line Sweep Select mesh type by Line Sweep Mesh By: Enter N1: 11 hit Enter and N2: 12 hit Enter Number of Flements Flement Size Activate **Multi_Select** ▼ Multi-Select Points of Line Pick curve L1_1 and L1_2 Mesh Parameters 11 🚔 N1 Multi-Select Inactivate Multi_Select Ratio: 1.0 Two End Pick curve **L2** N2: 12 🚔 then click Mesh It Ratio: 1.0 Two End Click **Accept** Click Done ✓ Native Path Tangent Center Align(move) L1_1: 11 💠 Align Closed Path L2: 12 💠 Wire Sampling Multi-Select 2 . New PID Part ID: Mesh It Accept Reject Done

Blade mesh...


- File > Import> IGES File (select /workshop4/blade.igs)
- Go to Mesh → NlineM
- Select mesh type by 2 Lines Shell
- Enter N1: 20 hit Enter and N2: 20 hit Enter
- Enter N3: 12 hit Enter and N4: 12 hit Enter
- Pick curve L1 and L2
- then click Mesh It
- Click Accept
- Click Done






Trim curve create...

- Go to Curve → Spline
- Inactivate Piecewise
- Pick nodes 1, 2, 3, 4, 5 and 6
- Click Apply
- Click Close






Trim blade...

- Go to EleTol → PtTrim
- Click Closest 3D proj dir.
- Select Parts, pick part 3 (blade)
- Select Curves, pick the trim curve
- Select Keep, pick a seed element need to keep
- Click Trim
- Click Accept
- Click Done


Save a project file...

- Go to File > Save > Save Project
- Enter a file name (save as /workshop4/fan.proj)
- Click Save



Model rotate...

- Click EdgGeo render buttons turn geometry off
- Go to EleTol → Transf
- Select Rotate
- Select Rot.Axis: Z
- Enter 120 at Rot. Angle
- Activate Copy Elem
- Activate Transfer
- Click Active in the General Selection interface
- Click Rotate+
- Click Accept
- Click Rotate+ again
- Click Accept
- Click Done




Duplicate nodes merge...

- Go to Ele Tol → DupNod
- Enter Tolerance: 0.1
- Activate Show Free Edges
- Click Show Dup Nodes
- Click Merge Dup Nodes
- Click Accept
- Click Done

Save a keyword file...

- Go to File > Save > Save Keyword
- Enter a file name (save as /workshop4/fan.k)
- Click Save




Workshop 5


Create a Keyword File (S-Rail to Rigidwall Impact)


- Mesh model
- Assign material and property
- Apply mass, constraint and velocity
- Rigid wall creation
- Define spot welding
- Save a keyword file
- Model comparison

Import and mesh IGES surfaces...

- Launch a new session of LS-PrePost
- File > Open > IGES File (select /workshop5/channel.igs and flat.igs both)
- Click Open in the IGES Read Options popup
- Go to Mesh → Auto Mesher
- Enter Elem Size: 6
- Click Active in the General Selection interface
- Click Mesh
- Click Accept
- Click Done








Define section property...

Click EdgGeo render buttons turn geometry off




- Go to Model → Keyword Manager
- Select All
- Expand SECTION
- Double-click "SHELL"
- Click NewID in the Keyword Input Form
- Enter TITLE: 1.0mm
- Enter ELFORM: 16 , T1: 1.0 (and hit the Enter key)
- Click Accept and Done




Define material property...

- Expand MAT in Keyword Manager
- Double-click "024-PIECEWISE_LINEAR_PLASTICITY"
- Click NewID in the Keyword Input Form
- Enter TITLE: Mild Steel
- Enter RO= 7.83e-6, E= 207.0, PR= 0.3, SIGY= 0.2, ETAN= 2.0
- Click Accept
- Click Done




Assign section and material...


- Go to Model → Part Data
- Select Assign
- Click All
- Click SECID
- Select "1.0mm" in the Link SECTION interface
- Click **Done** in Link SECTION interface
- Click MID
- Select "Mild Steel" in the Link MAT interface
- Click **Done** in Link MAT interface
- Click Apply
- Click Done



Add mass to end of rail...

- Click the **Top** render button
- Click the **Zoom In** render button and zoom in on the right end of the rail
- Go to Model → Create Entity
- Expand Element
- Select Mass
- Select Cre
- Enter Mass: 2.0
- Select Area in the General Selection interface
- Click and drag to select 1 row of nodes along the end of the rail (see 3)
- Click Save → To Buffer → Buffer1 in the General Selection interface
- Click Apply
- Select Show
- Select Label: MassValue
- Click Active in the General Selection interface







Create constraints at end of rail...


- Expand Boundary in entity creation
- Select Spc
- Select Cre
- Activate Y, Z, RX, RY, and RZ (everything except X)
- Click Load → From Buffer → Buffer1 in the General

Selection interface

Click Apply









Create initial velocities at end of rail...


- Expand Initial in entity creation
- Select Velocity
- Select Cre
- Enter Vx: -10.0
- Click Load → From Buffer → Buffer1 in the General Selection interface
- Click Apply






Create a rigid wall...


- Click the Auto Center (AutCen) render button
- Click the **Zoom In** render button and zoom in on the left end of the rail
- Expand Rigidwall in entity creation
- Select Rigidwall
- Select Cre
- Select Planar
- Select NX (you may have to scroll down)
- Pick any node at the left end of the rail






Create welds using a master weld file...


- Click the Auto Center (AutCen) render button
- Click the Wire render button
- Go to Mesh → Spot Welding
- Click Open in Spot Welding dialog box, load spotweld file (select /workshop5/welds.spot)
- Click Open in the Read Options popup
- Select Properties: File
- Click Browse (select /workshop5/spot.conf)
- Click Open in the Read Options popup
- Click Create
- Click Accept
- Click Done





Define contact...

- Go to Model → Keyword Manager
- Select All then expand CONTACT
- Double-click "AUTOMATIC_SINGLE_SURFACE"
- Click NewID in the Keyword Input Form
- Set **SSTYP: 2**
- Click the Link Button next to the SSID field
- Select "1 spotweld part set" in the Link SET interface
- Click **Done** in the Link SET interface





Set termination time...

- Go to Model → Keyword Manager
- Select All
- Expand CONTROL
- Double-click "TERMINATION"
- Enter ENDTIM: 10 in Keyword Input Form
- Click Accept
- Click Done

Set d3plot frequency...


- Expand **DATABASE** in Keyword Manager
- Double-click "BINARY_D3PLOT"
- Enter **DT**: **1** in Keyword Input Form
- Click Accept and Done





Set ASCII output frequency...

- Expand **DATABASE** in Keyword Manager
- Double-click "ASCII_option"
- Enter Default DT: 0.1 (and hit the Enter key)
- Activate GLSTAT
- Activate MATSUM
- Activate SWFORC (spotweld forces)
- Click Accept and Done




Save keyword file...

- File > Save As > Save Keyword As...
- Click Browse (save as /workshop5/srail.k) then Save
- Click Advanced...
- Click customize order: Expert
- Click **Ok** in the Advanced Setting interface
- Click Save in the Save Keyword interface


Compare a set of LS-DYNA Keyword files...

- Launch a new session of LS-PrePost
- File > Open > LS-DYNA Keyword File (select /workshop5/compare/belted1.k)
- File > Open > LS-DYNA Keyword File (select /workshop5/compare/belted2.k)
- Go to Model → MSelect
- Select Compare
- Click in the 1st Model field and select model 1
- Click in the 2nd Model field and select model 2
- Click Compare



Compare a set of LS-DYNA Keyword files...

- Select the Common Keywords tab
- Examine the RED items to identify differences



Workshop 6

Post-Processing

- Animation interface
- Fringe (contour) plotting
- Time history/ASCII data plotting
- Section cut
- Cross plotting
- Vector draw


Workshop 6


Load results d3plot file...

- Launch a new session of LS-PrePost
- File > Open > LS-DYNA Binary Plot (select /workshop6/d3plot), click Open
- Click the **Top** render button
- Click Animate Forward (click the Anim render button first if necessary)
- Decrease the animation speed using the slider

Generate a movie...


- File > Movie...
- Select Format : JPEG
- Enter File Name: animation1
- Click Start






Create a fringe contour plots...

- Go to Post → Fringe Component
- Click Ndv
- Select "result displacement" from the list
- Click Animate Forward
 (if the animation is not already playing)
- Click Stress
- Select "Von Mises stress" from the list
- Click Stop Animation




Modify range settings...


- Drag the slider to the last frame
- Go to Post → Fringe Range (FriRang)
- Select Avg: None
- Activate Reverse Colors
- Activate Ident Min and Max
- Enter No. Min/Max Entities: 1 (and hit Enter)
- Select Level: 20
- Click Animate Forward
 (if the animation is not already playing)
- Click Stop Animation
- Click the Shade Element (ShaEle) render button



Identify nodes and elements by ID...

- Drag the slider to the last frame
- Go to Post → Fringe Component
- Click Stress
- Select "Von Mises stress" from the list
- Go to Element Tools → Ident
- Select Node
- Activate Show Results in Identify
- Go to View (drop down menu)
- Activate Results On Screen in view
- Pick some nodes in the model
- Select Element
- Pick some elements by clicking
- Click Clear Node
- Click Clear Elem
- Click **Done** in Identify







Plot time history data...

- Go to Post → History
- Select Nodal
- Select "Z-displacement" from the list
- Pick 2 nodes on the Model
- Click Plot
- Click Quit in the Plot Window
- Select Element
- Select "Effective Stress (v-m)" from the list
- Pick an element on the plate
- Click Plot
- Click Quit in the Plot Window
- Click the Clear render button









Plot ASCII data...


- Go to Post → ASCII
- Select "rwforc *" from the top list
- Click Load
- Select the "Wall1" and "4-Normal Force" in the bottom list
- Activate Main in ASCII dialog
- Click Plot in ASCII dialog
- Click Show Port at XY-Plot Page Manager
- Right click Port1:*, select Control
- Activate **Timeline** in XY-Plot Port Control
- Click Animate Forward
- Click Hide at XY-Plot Page Manager
- Click Stop Animation






Cut a section plane...


- Rotate the model for an isometric view
- Go to Model → Section Plane
- Click NormX
- Click Cut
- Click Options
- Select Line Width: 3
- Click Animate Forward
- Click MP Anim
- Click MP Anim again stop the animation
- Click Stop Animation






Take section plane measurements...


- Click Model in Section Plane
- Click NormZ
- Click Cut
- Click Project View in Section Plane
- Click Meas in section plane(NOT Measur)
- Select 2Ln-Angle
- Click two points to form a line on the left top
- Click two points to form a line on the right top
- Click Options
- Activate ShMesh (section plane as a mesh)
- Click Curr State
- Click Write to save the section data (writes keyword file with beam elements only)
- Click **Done** in Section Plane interface






Output dynain file...

- Go to Post → Output
- Select Format: Dynain ASCII
- In the animation controls, advance to the last state
- Click Curr (current state)
- Click Write
 (writes a dynain ASCII file that contains stress, strain, and thickness information)




Save LS-PrePost database (post.db)...

- In the animation controls, advance to the desired state
- Go to Model → Assembly and Part (SelPart)
- Select "1 LSHELL1" and "2 LSHELL2" only
- Go to Element Tools → Blank
- Select Area in the General Selection interface
- Select Out
- Draw a box around a portion of the model
- File > Save As > Save Post.db As...
- In the Save PostProcess DB interface, select the data you want
- Click >>
- Enter a file name (select /workshop6/post.db)
- Click Write DB



View multiple models by split window...

- Launch a new session of LS-PrePost
- File > Open > LS-DYNA Binary Plot (select /workshop6/example2/d3plot), click Open
- File > Open > LS-DYNA Binary Plot (select /workshop6/elastic_plate/d3plot), click Open
- Go to Model → SplitW
- Select 2X1
- Activate Draw all areas
- Click Sync state1 button
- Click the Left render button
- Click Animate Forward




Split Window

Window Configuration


Create a cross plot...


- Launch a new session of LS-PrePost
- File > Open > LS-DYNA Binary Plot (select /workshop6/elastic_plate/d3plot), click Open
- Go to Post → ASCII
- Select "rcforc *"
- Click Load
- Select "SI-2" from the middle list
- Select "Z-force" from the lower list
- Click Plot
- Click Scale in PlotWindow-1
- Enter Y-scale: -1
- Click Apply
- Activate Autofit
- Click Save enter Filename: force_vs_time.crv
- Click Save in the bottom row of buttons
- Click Quit in PlotWindow-1



Create a cross plot (continued)...


- Go to Post → XYPlot
- Click Add (select /workshop6/elastic_plate/disp_vs_time.crv)
- Select Cross
- Select X-Axis
- Select "disp_vs_time.crv" in file
- Click "disp_vs_time.crv:2060" in Curve Names
- Select Y-Axis
- Select "force_vs_time.crv" in file
- Click "force_vs_time.crv:Sl 2" in Curve Names
- Click Plot






Set a reference point...


- Launch a new session of LS-PrePost
- File > Open > LS-DYNA Binary Plot (select /workshop6/belted/d3plot), click Open
- Click the **Left** render button
- Click Animate Forward
- Click Stop Animation
- Go to Post → Follow
- Pick any node on the structure
- Click Apply
- Click Animate Forward
- Click Reset (in the Follow interface)
- Click **Done** (in the Follow interface)



View velocity vectors...

- Go to Post → Vector
- Select Velocity from the drop down menu
- Click Apply
- Click Next State (in the animation interface) to step through the animation frame by frame
- Click Done





Colors, Groups, and Views...

- Go to Model → Part Color
- Click Lmap (select /workshop6/colors_groups_views/colors)
- Go to Model → Groups
- Click Load (select /workshop6/colors_groups_views/groups)
- Select "dummy" from the list
- Click Select
- Go to Model → Views
- Click Load (select /workshop6/colors_groups_views/views)
- Select "View_01" from the list
- Click Select
- Click Done

