

R15.0.1 Release Notes

March 6, 2024

- 1 Release notes revision
- 2 License
- 3 Documentation
- 4 Notes
- 5 Bug Fixes
 - 5.1 Forming Analysis

1 Release notes revision

This file constitutes revision 0 of the release notes for LS-DYNA version R15.0.1.

2 License

The string “REVISION 15” must appear in the LS-DYNA license file to run version R15.0.1. Please contact your LS-DYNA distributor or your Ansys sales representative if you need to have your license updated.

3 Documentation

The R15.0 User’s Manuals provide documentation for R15.0.1. To download these manuals, go to <https://lsdyna.ansys.com/manuals/>.

4 Notes

The remainder of this file briefly describes the bug in version R15.0.0 that led to R15.0.1. To see the release notes for R15.0.0, go to https://ftp.lstc.com/anonymous/outgoing/-support/FAQ/ReleaseNotes/Release_Notes_LS-DYNA_R15_0_0_rev0.html.

5 Bug Fixes

5.1 Forming Analysis

1. Fixed bug in Windows MPP LS-DYNA for metal forming problems that involved adaptivity. The bug caused the run to fail due to an i/o issue.

